

REPORT of SURVEY for REPAIRS, &c.

No. 40045  
No. in Survey held at London  
Reg. Book. A 739 on the Iron S. Aminta now changed to Pluto.  
Date, first Survey 22<sup>nd</sup> Dec<sup>r</sup>/80 Last Survey 1<sup>st</sup> Feb<sup>y</sup> 1881  
Master  
TONNAGE under Tonnage Deck 1132  
Ditto of Spar Deck, or Awning Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage 1132  
Crew Space, as per Rule  
Register Tonnage on Beam 1110  
Engine Room  
Reg. Tons as St<sup>r</sup>mer, cut on Bm.  
Built at Liverpool  
When built 1862  
Owners F. Lacioz.  
Port belonging to Hamburg  
Residence Hamburg  
By whom built Jones.  
Destined Voyage  
If Surveyed Afloat or in Dry Dock In the West India Dry Dock.  
(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.  
Last Survey, No. 22181 Port Iron  
REPAIRS, OR EXAMINATION AS PER RULE  
Cause of Repairs to be clearly stated.  
Classed S.S. Liv. N<sup>o</sup> 3-74.  
S.S. Liv. N<sup>o</sup> 1-78.  
Character in Register Book.  
\*A.1.  
10.78.

The present Owner has been applied to in reference to the classification of this vessel and has declined having any survey held. Before there was a change of Ownership, application was made to us by Capt<sup>n</sup> Pearne, the then Owner's Representative, to survey the bowsprit of the vessel, which was broken off and lying in Messrs. J & R. B. Brown's Dockyard Poplar. Directions were given by us for the repairs of the bowsprit and attended to until its completion. The broken plates were renewed and the bowsprit doubled for about 10 feet in way of the knight heads &c. The bottom has been examined, cleaned & coated.

Present Condition of the  
Decks  
Waterways  
Lower Planks  
Sheerstrake  
Topside  
Wales  
Plank (Bottom) and Counter  
Treenails  
Breasthooks and Stemson  
Transoms, Pointers, and Crutches  
Timbers of the Frame at the openings  
Ditto Ditto at other places  
Keelsons  
Clamps and Shelves  
Ceiling  
Rudder  
Copper (or Y.M.) When put on  
Caulking of Bottom, Deck, & Waterways  
Windlass and Capstan  
Pumps  
Boats  
Masts, Yards, &c.  
Condition, how ascertained  
Sails  
Anchors No. of  
Cables  
Hawsers and Warps  
Standing & Running Rigging

Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches  
General Observations, Opinion as to Class, &c. The present Owner having refused survey on the vessel, the matter is now left for the consideration of the Committee. We would however suggest that the former Owner should be charged £2-2s. for the services rendered in connection with the bowsprit. Messrs. Ismay, Imrie & Co. are the agents for the former Owners.

The Amount of Entry Fee ... £ : : received by me, }  
Special ... £ 2.2 : : 188  
Certificate (if required) } £ : :  
to be sent as per margin... }  
(Travelling Expenses, if any, £ )  
Committee's Minute Friday, February 4th. 1881.  
Character assigned  
J. H. Truscott.  
Supt. Lloyd's Register of British and Foreign Shipping.  
Lloyd's Register Foundation