

(40185)

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 11/3/81)

No. in Reg. Book. Survey held at London Date, first Survey _____ and Last Survey Mar. 4th 1881

538 on the Machinery of the S. S. "Jubilee" (Number of Visits 1)

Tonnage, Gross 790 Built at Sunderland When built 1867

Ditto, Net 496 Owners Lambert Bros. Port belonging to London

Diameter of Cylinder 27" + 47" Engines made by Comp. R. & M. Co. When made 1873

Length of Stroke 30" Boilers made by Ditto When made 1873

Pressure of Steam 58" If Surveyed Afloat or in Dry Dock Dry dock Years assigned _____ Character in Register Book. 85A1

Registered Horse Power 90 Classed _____

Last Survey No. _____ Port Slays M. C. 281

Particulars of Repairs and Examination For Annual Survey -

(State cause of Repairs.)

Vessel placed in dry dock, sea connections examined & found to be in good condition. -
Propeller & its connections in good condition.
Tail shaft found to be a good working fit in Stern Bush.

(State if repairs are also sent on the Hull of the Ship, and subsequent Repairs and Examinations, to be clearly stated.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears eligible to remain as classed.

Entry or Registering Fee ... £ : :
Survey Fee ... £ — : — : received by me,
Certificate (if required) ... £ : : 188 }
to be sent as per margin.

(Travelling Expenses, if any, £ _____)


Committee's Minute _____

Friday, March, 18th. 1881.

Assigned _____

Geo. C. Wilkinson

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

(Insert Character precisely as in the Register Book.)

LON/665-0277

It is submitted that Mrs. [unclear]

is eligible to have the
notification Lloyd M.C.
2.81 retained -

RM
10/3/81



© 2021
Lloyd's Register
Foundation