

(40512)

Report of Survey for Repairs of Engines and Boilers.

(Received at London Office, 1-11-81)

No. _____

No. in Reg. Book. *886* Survey held at *London* Date, first Survey _____ and Last Survey *Oct. 28th 1881*

on the Machinery of the *S.S. "Ann Webster"* (Number of Visits *1*)

Tonnage, Gross *771* Built at *Hartlepool* When built *1870*

Ditto, Net *682* Owners *Comml. Ste. Shp Co.* Port belonging to *London*

Diameter of Cylinder *25" x 18"* Engines made by *Richardson & Sons* When made *1870*

Length of Stroke *36* Boilers made by *Ditto.* When made *1880.*

Pressure of Steam *75 lbs.* If Surveyed Afloat or in Dry Dock *Limited Dock* (State name of Dock.)

Registered Horse Power *96.* Classified *90A1*

Last Survey No. _____ Port _____ *B.M.S. 12.80.*

Particulars of Repairs and Examination For Annual Survey -

(State cause of Repairs.)

Vessel placed in dry dock sea connections examined found to be in good condition. Propeller & its connections found to be sound. Stern Bush worn down 1/8"

General Observations, Opinion, and Recommendation:— *As far as seen this vessel appears eligible to remain as classed*

Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ : : received by me, }
 Certificate (if required) ... £ : : 188 }
 to be sent as per margin.
 (Travelling Expenses, if any, £ _____)

G. E. Wilkinson
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute _____ Tuesday, November, 15th, 1881.
 Assigned _____



LON666-0024

(Condition of Engines and Boilers, and subsequent Repairs.)

(Insert Character precisely as in the Register Book.)

This vessel has been examined
at an annual survey, submitted
The ste is eligible to remain
as classed -

M 31. 10. 81



© 2021
Lloyd's Register
Foundation

Boilers of Survey for Boilers of Engines and Boilers