

Report of Survey for Repairs of Engines and Boilers.

40626

No. _____ (Received at London Office, 29. 6. 81.)

No. in Reg. Book. Survey held at London Date, first Survey and Last Survey June 22nd 1881

~~178~~ ¹⁵⁹ on the Machinery of the S. S. "Hastings" (Number of Visits 1)

Tonnage, Gross 696 Built at R. Shields When built 1864

Ditto, Net 473 Owners Harris & Dixon Port belonging to London

Diameter of Cylinders 38" Engines made by Palmer's Co. When made 1869

Length of Stroke 30" Boilers made by _____ When made 1876

Pressure of Steam 35 lbs. If Surveyed Afloat or in Dry Dock Similar dry dock Classified AB 1

Registered Horse Power 90. Years assigned. Character in Register Book.

Last Survey No. 40179 Port Lon. Lloyds M.C. 8. 79.

Particulars of Repairs and Examination In Annual Survey—

Vessel placed in dry dock sea connections examined and found to be in good condition. Propeller disconnected, Tail shaft examined which was found to be somewhat corroded between the liners. Liners found to be tight on shaft. Stern bush retained with lignum vitae and the Propeller replaced.

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears eligible to remain as classed

Entry or Registering Fee ... £ : :
 Survey Fee ... £ — : : received by me,
 Certificate (if required) ... £ : : 188

(Travelling Expenses, if any, £)


Committee's Minute

Assigned

Friday, July, 22nd 1881.

W. H. W. W.
J. B. W.

Geo. E. Merriamson
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
 Foundation

LON 666-0289

It is submitted that
this vessel is eligible
to remain as closed

M

29/6/82



© 2021

Lloyd's Register
Foundation