

Report of Survey for Repairs of Engines and Boilers.

40728

(Received at London Office, 22.8.81)

No. _____

No. in Reg. Book. *623* Survey held at *London* Date, first Survey *15 Aug* Last Survey *15 Aug* 188*1*

on the Machinery of the *S. S. "Shoreham"* (Number of Visits *21*)

Tonnage, Gross	<i>491</i>	Built at	<i>Port Glasgow</i>	When built	<i>1872</i>
Ditto, Net	<i>293</i>	Owners	<i>S. Clarke & Co</i>	Port belonging to	<i>London</i>
Diameter of Cylinder	<i>34 42</i>	Engines made by	<i>Walker Henderson & Co</i>	When made	<i>1872</i>
Length of Stroke	<i>30</i>	Boilers made by		When made	<i>1879</i>
Pressure of Steam	<i>60</i>	If Surveyed Afloat or in Dry Dock	<i>Fletchers & Co</i>	Classed	<i>90 A1</i>
Registered Horse Power	<i>80</i>	(State name of Dock.)		Years assigned.	<i>2.81.</i>
Last Survey No.		Port		<i>Lloyd's M C 2.81.</i>	

Particulars of Repairs and Examination *Annual*

(State cause of Repairs.)

Examined Sea cocks & connections found them in good order.
The lignum vite in stern bush had worn down and has been renewed.

state if a ... Also sent on the Hull of the Ship ... and subsequent Repairs and Examinations, to be clearly stated.

Form No. 9-3000, 29/1/81.

General Observations, Opinion, and Recommendation:— *The machinery of this vessel appears in good working order and eligible in my opinion to remain as classed.*


Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ : :
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)

received by me,
26 Aug 1881

C. E. Bromeyer
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute *Friday, August, 26th 1881.*

Assigned



Lloyd's Register Foundation

Insert Character precisely as in the Register Book.

0170 99966

It is submitted that this vessel
is eligible to remain as
Classed

JM

20/8/81



© 2021

Lloyd's Register
Foundation