

40945

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 22. 10. 81)

No. in Reg. Book. Survey held at London Date, first Survey Oct. 17th Last Survey Oct. 17th 1881.

553 on the Machinery of the S. S. "Potaro" (Number of Visits 1)

Tonnage, Gross <u>1271</u>	Built at <u>Hartlepool</u>	When built <u>1879</u>
Ditto, Net <u>818</u>	Owners <u>Steel Young & Co.</u>	Port belonging to <u>London</u>
Diameter of Cylinder <u>28" & 53"</u>	Engines made by <u>J. Richardson & Sons</u>	When made <u>1879</u>
Length of Stroke <u>33"</u>	Boilers made by <u>Ditto</u>	When made <u>1879</u>
Pressure of Steam <u>70 lbs.</u>	If Surveyed Afloat or in Dry Dock <u>Bridge Dock</u>	Classed <u>100A1</u>
Registered Horse Power <u>110</u>	(State name of Dock.)	Character in Register Book.

Last Survey No. _____ Port Lloyd's M. C. 8. 79

Particulars of Repairs and Examination For Annual Survey -

(State cause of Repairs.)
Vessel placed in dry dock sea connections examined
found to be in good condition. Propeller & its connections
found sound. Tail shaft down 1/4" in Stern Bush.

General Observations, Opinion, and Recommendation:— As far as seen this
vessel appears eligible to remain as classed


Entry or Registering Fee... .. £ : :	
Survey Fee (per Section 28) £ : :	received by me,
Certificate (if required) £ : :	188

(Travelling Expenses, if any, £ _____)

Committee's Minute Friday November, 4th 1881.

Assigned _____

Geo. C. Richardson
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

LON667-0095

(State if Report is also sent on the Hull of the Ship...)
(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)
(The Surveyors are requested not to write on or below the space for Committee's Minute).

(Insert Character precisely as in the Register Book.)

It is submitted that this
vessel is eligible to
remain as classed

M
2/10/81



© 2021
Lloyd's Register
Foundation

Lloyd's Register of Shipping and Boilers