

Report of Survey for Repairs of Engines and Boilers.

No.

No. in Survey held at

London

Date, first Survey 30 Sept. Last Survey 30 Nov 1881.

1455 on the Machinery of the

S. J. Arena

(Number of Visits 6)

Tonnage, Gross

728

Built at

Lundeland.

When built

1873

Ditto, Net

459

Owners

W Thorburn

Port belonging to

Uddvalla

Diameter of Cylinder

24 & 48

Engines made by

Onsburn Eng Wks

When made

1873

Length of Stroke

33"

Boilers made by

"

When made

1873

Pressure of Steam

50

If Surveyed Afloat or in Dry Dock

Afloat in Commercial Dk.

Years assigned.

Character in Register Book.

Registered Horse Power

95

(State name of Dock.)

Classed

90 A1

Last Survey No.

40915

Port

Lon

S. S. 401-48

9.81.

B & M S. 9.80

Particulars of Repairs and Examination

Annual. (Age of boilers)

(State cause of Repairs.)

Examined boiler and found it to be in a good condition. The donkey stop valve was leaking and had filled the super-heater which could not be examined till a month later and was then found to be in good condition.

The safety valves (lever) are loaded to 65 lbs per square that being the original working pressure. The recorded working pressure had been reduced when the boilers were tested to 100 & about 12 months ago. For particulars see letter by C A Miller 20/11/81.

General Observations, Opinion, and Recommendation:— As far as seen the boiler appears to be in a safe working condition for a pressure of 65 & and is in my opinion eligible to remain as classed and to have B.S. 11.81. and 65 lbs instead of 50 lbs recorded in the Register Book.

Entry or Registering Fee... £ " : " : "

Survey Fee (per Section 28) ... £ 3 : 3 : - received by me,

Certificate (if required) ... £ : : 15/11/1881

(Travelling Expenses, if any, £)

Committee's Minute

Tuesday, December, 13th, 1881.

Assigned

B.S. 11.81

Surveyor

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register Foundation

LONG67-0112

It is submitted that this vessel
is eligible to have the notifi-
cation BS 11. 81 Recorded.
Subject to the Boiler being
again tested in 12 months
as per rule

M TBW

5/12/81



© 2021

Lloyd's Register
Foundation