

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 9.6.82)
 No. in Reg. Book. Survey held at London Date, first Survey _____ and Last Survey May 20th 1882

255 on the Machinery of the S.S. "Eldorado" (Number of Visits 2)

Tonnage, Gross <u>3332</u>	Built at <u>Stull</u>	When built <u>1873</u>
Ditto, Net <u>2157</u>	Owners <u>A. Gray + E. S. Dawes</u>	Port belonging to <u>Glasgow</u>
Diameter of Cylinder <u>47 + 90</u>	Engines made by <u>Carle's Co.</u>	When made <u>1873</u>
Length of Stroke <u>50</u>	Boilers made by <u>Ditto</u>	When made <u>1873</u>
Pressure of Steam <u>60lbs.</u>	If Surveyed Afloat or in Dry Dock <u>Alth. D. Dr.</u>	Years assigned _____ Character in Register Book. <u>100A1</u>
Registered Horse Power <u>450</u>	(State name of Dock.)	Classed _____
Last Survey No. _____	Port _____	<u>Lloyds M.C. 2. 82</u>

Particulars of Repairs and Examination In Annual Survey

(State cause of Repairs.)

Vessel placed in dry dock sea connections examined & found to be in good condition. Propeller & its connections found & the tail shaft down 1/4" in Stern Bush.

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears eligible to remain as classed.

Submitted that this vessel is eligible to remain as classed - M.S. 6.82

Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ : : received by me,
 Certificate (if required) ... £ : : 188
 to be sent as per margin.
 (Travelling Expenses, if any, £ _____)

Geo. S. Murrison
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Tuesday, 13th June, 1882.

Assigned _____



Lloyd's Register Foundation

Form No. 9, 20th 1881. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in the Register Book.