

# ANNUAL SURVEYS.

41597  
19 June 82

No. \_\_\_\_\_ Survey held at London Date, first Survey June 2<sup>d</sup> Last Survey June 8<sup>th</sup> 1882  
 No. in on the SS Europa Master Hall  
 Reg. Book. 975 Tonnage 424 Built at Newcastle When built 1862-3  
676 By whom built Palmer Bros Owners Genltn Ship Co  
 Port belonging to London Destined Voyage Medit<sup>n</sup>  
 If Surveyed Afloat or in Dry Dock Porton Victoria St

Last Survey, No. 3300 Port of London Years assigned. 95 A1 6.81  
Character in Register Book. SS Genltn 1.79  
S.S. class - 75

Present Condition of the Decks <u>good</u>	Treenails <u>Rivets</u>	good
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	"
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	"
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	"
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	"
Planksheers <u>"</u>	Keelsons <u>"</u>	"
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	"
Topsides <u>"</u>	Ceiling <u>"</u>	"
Wales <u>"</u>	Rudder <u>"</u>	"
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Coated</u> When put on <u>Nov</u>	"
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	"
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	"
General Observations, Opinion as to Class, &c. <u>Bottom is coated</u>	Cargo and Main Hatchways <u>Good</u>	Hatches <u>"</u>

*She is now in good condition and eligible to remain as classed, a few butt planks renewed under the beam which Yellow Pine.*

Committee's Minute Tuesday, 20<sup>th</sup> June, 1882.  
 Character assigned 95 A1 Senhouse Martindale  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_ Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Years assigned. \_\_\_\_\_  
Character in Register Book. \_\_\_\_\_

Present Condition of the Decks _____	Treenails _____	_____
Waterways _____	Breasthooks and Stenson _____	_____
Comings _____	Transoms, Pointers, and Crutches _____	_____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	_____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	_____
Planksheers _____	Keelsons _____	_____
Sheerstrakes _____	Clamps and Shelves _____	_____
Topsides _____	Ceiling _____	_____
Wales _____	Rudder _____	_____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	_____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	_____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	_____
General Observations, Opinion as to Class, &c. _____	Cargo and Main Hatchways _____	Hatches _____

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_ Senhouse Martindale  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) \_\_\_\_\_ Paid \_\_\_\_\_ 18 \_\_\_\_\_



LON 669-0228