

Report of Survey for Repairs of Engines and Boilers.

41626

(Received at London Office, 18 7 82)

No. _____

No. in Reg. Book. *191* Survey held at *London* Date, first Survey *June 22* Last Survey *June 23* 1882.

on the Machinery of the *S. S. "Manora"* (Number of Visits *2*)

Tonnage, Gross <i>3242</i>	Built at <i>Dumbarton</i>	When built <i>1878</i>
Ditto, Net <i>2120</i>	Owners <i>D. Macneil & P. Denny</i>	Port belonging to <i>Glasgow</i>
Diameter of Cylinder <i>50" & 86"</i>	Engines made by <i>Denny & Co</i>	When made <i>1878</i>
Length of Stroke <i>54"</i>	Boilers made by <i>Do.</i>	When made <i>1878</i>
Pressure of Steam <i>70 lbs.</i>	If Surveyed Afloat or in Dry Dock <i>Albert Dock</i>	Classed <i>100A1</i>
Registered Horse Power <i>500</i>	(State name of Dock.)	Years assigned. Character in Register Book.

Last Survey No. _____ Port *L.M.C. 4.78.*

Particulars of Repairs and Examination For Annual Survey

(State cause of Repairs.)

Vessel placed in dry dock, sea connections examined & found to be in good condition. Propeller disconnected, ~~and~~ Stern bush repaired with lignum vitae & propeller replaced.

(State of Repairs and Examination, to be clearly stated.)
 (Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

(Insert Character precisely as in the Register Book.)

General Observations, Opinion, and Recommendation:— *As far as seen this vessel appears eligible to remain as classed.*

Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ — : — : received by me,
 Certificate (if required) ... £ : : : 188 }
 to be sent as per margin.

(Travelling Expenses, if any, £ _____)

Geo. E. Milner
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute *Friday, 21st July, 1882.*

Assigned



LON 608-0390

Form No. 9-3000, 1/11/81.

It is submitted that this vessel is
eligible to remain as classed

M-17/7/82

[Faint, mostly illegible handwritten text in Cyrillic script, likely a technical report or certificate.]



© 2021
Lloyd's Register
Foundation

Department of Survey for Boilers and Engines of the Government of India