

# Report of Survey for Repairs of Engines and Boilers.

42546

(Received at London Office, 16. 1. 83.)

No. 337 on the Machinery of the S. S. John Pender (Number of Visits 3)

No. in Reg. Book. 1213 Survey held at London Date, first Survey 13 Dec 1882 Last Survey 6 Jan 1883

Tonnage, Gross 1213 Built at Inverkeithing When built 1875

Ditto, Net 706 Owners Eastern Telegraph Co Port belonging to London

Diameter of Cylinder 24 1/2 48 1/2 Engines made by J. Scott & Sons When made 1875

Length of Stroke 36 Boilers made by  When made 1875

Pressure of Steam 70 If Surveyed Afloat or in Dry Dock Penders Dry Dock (State name of Dock.)

Registered Horse Power 98 Years assigned 90 A1 Character in Register Book 10. 81.

Last Survey No.  Port L.M.C. 9. 81.

## Particulars of Repairs and Examination

Special Survey No 2.

Examined Leacocks & connections & found them good

Examined Boilers and found them in a good condition

The safety valves are loaded with lever & weights to 70 lbs.

Examined Slide valves, high and low pressure cylinders

pumps, crankshaft and thrust block & found them good.

Propeller has been unshipped & refitted.

## General Observations, Opinion, and Recommendation:—

The machinery of this vessel appears to be in a safe working condition and the vessel is in my opinion eligible to have the notification L.M.C. 1. 83 recorded in the Register Book

Entry or Registering Fee... £ 3 : 3 : 0 received by me, F.F.E.

Survey Fee (per Section 28) ... £ 2 : 6 : 0 1883

Certificate (if required) ... £  :  :

(Travelling Expenses, if any, £ )

C. D. Brown  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUESDAY 12 JUNE 1883 188

Assigned

M. L. 1883



© 2021 Lloyd's Register Foundation

LON 670-0344

(State of Repair, also sent on the Hull of Examination, to be clearly stated, and subsequent Repairs)

Insert Character precisely as in the Register Book.



It is submitted that this vessel is eligible  
to have the notification L M b 1.43 recorded  
subject to the boilers being re surveyed in  
12 months as per Rule

W F

15/1/83



© 2021

Lloyd's Register  
Foundation