

Report of Survey for Repairs of Engines and Boilers.

No. 150 on the Machinery of the S.S. "Hastings" (Number of Visits 1)  
No. in Reg. Book. Survey held at London Date, first Survey and Last Survey Nov 2nd 1883

Tonnage, Gross 696 Built at N. Shields When built 1864  
Ditto, Net 473 Owners Harris & Dixon Port belonging to London  
Diameter of Cylinder 38 Engines made by Palmers Co. When made 1869  
Length of Stroke 30 Boilers made by When made 1876  
Pressure of Steam 35 lbs. If Surveyed Afloat or in Dry Dock Stawards' Yard. Classified AB 1  
Registered Horse Power 90 (State name of Dock.) Years assigned. Character in Register Book.  
Last Survey No. 16834 Port New T.M.C. 3.79. B.S. 5.83.

Particulars of Repairs and Examination On account of damage to propeller  
(State cause of Repairs.)  
Propeller found to have three of the blades broken this has been removed, the tail shaft examined and found to be in good condition & a new propeller fitted.

It is submitted that this vessel is eligible to remain as classed  
no classed 11/11/83

General Observations, Opinion, and Recommendation:— As far as seen this vessel appears eligible to remain as classed.

Entry or Registering Fee... £ : :  
Survey Fee (per Section 28) ... £ 0 : 0 : — received by me,  
Certificate (if required) ... £ : : 188  
to be sent as per margin.  
(Travelling Expenses, if any, £ )

Committee's Minute TUESDAY 20 NOV 1883 188  
Assigned J.W. No new reasons  
SP Damage to 11/11/83  
Geo. E. Milnerison.  
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



(State if Report is also sent on the Hull of the Ship)  
(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)  
[Form No. 9—3000, 20/5/82.]  
(The Surveyors are requested not to write on or below the space for Committee's Minute).

Insert Character precisely as in the Register Book.

40N671-0359