

ANNUAL SURVEYS.

43661

(Received at London Office) THURSDAY 3 APRIL 1884

No. 25 Survey held at London Date, first Survey 19th July Last Survey 22nd March 1884
 No. in Reg. Book. on the BK Pak Wan (Composite) Master R. E. Begg
 Tonnage 818 Built at Sunderland When built 1863 5
 Under Dk. 725 By whom built J. Peverall Owners A. Lawrence
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Nelson Dry Dock Society's Freeboard (if assigned) as painted on Ship
 (State Name of Dock.)

Last Survey, No. 42386 Port of Lon.

Present Condition of the Decks <u>Good</u>	Treenails, <u>bolts, Drims</u> <u>Good</u>	Classed <u>15A1. 3.83</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>Cont Lon Dec 78. 10 yrs</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>H.T. Jan 83.</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Windlass and Capstan <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Pumps <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Boats <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Masts, Yards, &c. <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Condition, how ascertained <u>From SK</u>
Wales <u>"</u>	Rudder <u>"</u>	Sails <u>Good</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Y. Metal</u> When put on <u>3.82</u>	Anchors, No. of <u>3 Bros. 82 & 84</u>
Engine Room Skylights <u>"</u>	Caulking of <u>Patched now</u>	Cables <u>Range & examined - Good</u>
Coal Bunkers, Openings, Lids, &c. <u>"</u>	Bottom, Deck, & Waterways <u>Good</u>	Hawsers and Warps <u>"</u>
Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>	Standing and Running Rigging <u>"</u>
Hatches <u>"</u>		

General Observations, Opinion as to Class, &c. At the present time surveyed in the dry dock for damage, but on a careful examination a short piece of false keel found and a few sheets and pieces of yellow metal were found to be off the keel & bottom, and have now been put to right. She is in an efficient state and eligible to remain as classed.

Committee's Minute

Character assigned

FRIDAY 4 APRIL 1884

Senhouse Masthead

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 25 Survey held at London Date, first Survey 19th July Last Survey 22nd March 1884
 No. in Reg. Book. on the BK Pak Wan (Composite) Master R. E. Begg
 Tonnage 818 Built at Sunderland When built 1863 5
 Under Dk. 725 By whom built J. Peverall Owners A. Lawrence
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Nelson Dry Dock Society's Freeboard (if assigned) as painted on Ship
 (State Name of Dock.)

Last Survey, No. 42386 Port of Lon. Classed 15A1. 3.83

Present Condition of the Decks <u>Good</u>	Treenails <u>Good</u>	Classed <u>15A1. 3.83</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>Cont Lon Dec 78. 10 yrs</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>H.T. Jan 83.</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Windlass and Capstan <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Pumps <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Boats <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Masts, Yards, &c. <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Condition, how ascertained <u>From SK</u>
Wales <u>"</u>	Rudder <u>"</u>	Sails <u>Good</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Y. Metal</u> When put on <u>3.82</u>	Anchors, No. of <u>3 Bros. 82 & 84</u>
Engine Room Skylights <u>"</u>	Caulking of <u>Patched now</u>	Cables <u>Range & examined - Good</u>
Coal Bunkers, Openings, Lids, &c. <u>"</u>	Bottom, Deck, & Waterways <u>Good</u>	Hawsers and Warps <u>"</u>
Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>	Standing and Running Rigging <u>"</u>
Hatches <u>"</u>		

General Observations, Opinion as to Class, &c. At the present time surveyed in the dry dock for damage, but on a careful examination a short piece of false keel found and a few sheets and pieces of yellow metal were found to be off the keel & bottom, and have now been put to right. She is in an efficient state and eligible to remain as classed.

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON672-0327

ANNUAL SURVEYS.

Part II

Annual Survey of Shipping

1872

(Continued from Part I)

When built

Owner

Particulars

Builder's Certificate (if assigned as printed on Ship)

Classed

1872

1873

1874

1875

1876

1877

1878

1879

1880

1881

1882

1883

1884

1885

1886

1887

1888

1889

1890

1891

1892

1893

1894

1895

1896

1897

1898

1899

1900

1901

1902

1903

1904

1905

1906

1907

1908

1909

1910



© 2021

Lloyd's Register Foundation