

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 11. 8. 85.)

No. in Reg. Book. Survey held at London Date, first Survey Mar. 6th Last Survey Mar. 9th 1885

on the Machinery of the S. S. "Ternit" (Number of Visits 3)

Tonnage, Gross 2057 Built at Sunderland When built 1871

Ditto, Net 1349 Owners C. M. Norwood & Co. Port belonging to London

Diameter of Cylinder 37 & 70 Engines made by Thompson Boyd & Co. When made 1871

Length of Stroke 36 Boilers made by _____ When made 1880

Pressure of Steam 75 lbs. If Surveyed Afloat or in Dry Dock Pontoon U.D. (State name of Dock.)

Registered Horse Power 250 Years assigned. Character in Register Book. 100 A1

Last Survey No. _____ Port L.M.C. 12.80

Particulars of Repairs and Examination For Annual Survey

(State cause of Repairs.)

Vessel placed on Pontoon, sea connections examined & found to be in good condition. Propeller disconnected tail shaft drawn out, the spare tail shaft & spare propeller fitted, the stern bush did not require to be renewed. A new tail shaft has been made & is now ready at the Pontoon, Victoria Dock.

General Observations, Opinion, and Recommendation:— As far as seen of the machinery this vessel appears eligible to remain as classed.

Entry or Registering Fee... £ : :
(per Section 27.)


Survey Fee (per Section 28) ... £ : : received by me, }
Certificate (if required) ... £ : : 188
to be sent as per margin.

(Travelling Expenses, if any, £)

Committee's Minute TUESDAY 27 OCT 1885 188

Assigned

Geo. E. Trevelyan
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

LN674-0340