

REPORT of SURVEY for REPAIRS, &c.

Received in London Office.

SAT 11 APRIL 1885

No. *5* Survey held at *London* Date, First Survey *11/2/85* Last Survey *3/3/1885*
 Reg. Book. *5* on file *Sacia* (No. of Visits) Master *Thomson*

TONNAGE *1423* Built at *Sunderland* By whom *Laing* When *1867* - *1885*
 NET *1423* Owners *Ind Rub Gut Perla & Co* Port belonging to *London*
 GROSS *1856* Owners' Address *James Rd* Destined Voyage *West Indies*
 UNDER DK. *1252* (if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock *Dry D* Name of Dock *James Rd* Years assigned, if a Wood Ship. Character in Register Book. *B 1*

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins. *Classed*
 Last Survey, No. *4392* Port *Lon* *S.S. No 3-80* *4/84*

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.) Society's Freeboard (if assigned) in salt water ft. ins. as painted on Ship. in fresh water ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE *Completion of Special Survey No 1.*

This vessel was placed in dry dock, the bottom examined cleaned and painted. The ceiling considerably in excess of the Rule lifted & the cement found adhering satisfactorily to the iron. The masts spars and general equipment examined except chain cables which were ranged 4.84 see London Report No 43927. The double bottom tested by a head of water to the height of the light water line.

Repairs:- The foretop sail yard renewed with pitch pine. Cap of main mast lowered 9 inches.

The deck was examined and found to be somewhat piced & worn in places, it appears however to be perfectly tight & sound. The owners propose to renew deck within the year.

PRESENT CONDITION OF THE		Good		Good		Good		Good	
Decks	Good	Plank (Bottom) & Counter	Good	Ceiling	Good	Boats	Good	Boats	Good
WAYS	✓	Nails or Rivets	✓	Rudder	✓	Masts, Yards, &c.	✓	Masts, Yards, &c.	✓
DK. Beams & Fastenings	✓	Breasthooks & Stemson	✓	Windlass & Capstan	✓	Condition, how ascertained	examined	Condition, how ascertained	examined
DK. Beams & Fastenings	✓	Transoms, Pointers, & Crutches	✓	Pumps	✓	Sails	2 sent good	Sails	2 sent good
Keelsons	✓	Timbers of Frame at the openings	✓	Cement (if Iron Ship)	✓	Anchors	No. 210, 18. 2K	Anchors	No. 210, 18. 2K
Sheerstrakes	✓	Plank ditto at other places	✓	Caulking of Bot'm, D'k, & Watrways	✓	Cables	what seen good	Cables	what seen good
Topsides	✓	Keelsons	✓	Copper, or Y.M. (State if on Felt.)	✓	Hawsers & Warps	Sufficient	Hawsers & Warps	Sufficient
Wales	✓	Clamps & Shelves	✓	When put on	✓	Standing & Running Rigging	good	Standing & Running Rigging	good
Engine Room Skylights	✓	Coal Bunker, Openings, Lids, &c.	✓	Scuppers	good	Cargo & Main Hatchways	good	Cargo & Main Hatchways	good

General Observations, Opinion as to Class, &c.:

This vessel appears to be in a sound & efficient condition eligible to remain as classed. The owners propose to renew deck within the year (see guarantee attached). It is submitted that the Special Survey No 1 be recorded in the Register Book.

Entry Fee (if chargeable) per Scale I., Sec. 27. £ - : - :
 Office Fee (if chargeable) per Scale II., Sec. 27. £ - : - :
 Survey Fee (per Section 28) £ 4 4 0
 Special Damage Fee (if any) (per Sec. 28) £ - : - :
 *Certificate (if required) See margin £ - : - :
 Travelling Expenses (if chargeable) £ - : - :
 Second Surveyor's Fee (if any) £ - : - :
 Committee's Minute
 Character assigned *None Deck*

received by me *Edwa Geo Lerner*
J. H. Truscott
 Surveyor to Lloyd's Register of British & Foreign Shipping.
 TUESDAY 14 APRIL 1885
 LLOYD'S REGISTER FOUNDATION
 LONG 674-0437