

Report of Survey for Repairs, &c., of Engines & Boilers.

45740

No. _____ (Received at London Office, THURS 24 DEC 1885)

No. in Reg. Book. Survey held at London Date, first Survey Dec: 7th Last Survey Dec: 15 1885

764 on the Machinery of the S.S. "Merikara" (Number of Visits 3)
Year Month

Tonnage, Gross 47 + 82 Built at Dumbarton When built 1875-7
Year Month

Ditto, Net 4 Owners D. McNeil & P. Denny Port belonging to Glasgow
Year

Diameter of Cylinder 47 + 82 Engines made by Denny & Co. When made 1875
Year

Length of Stroke 48 Boilers made by Do. When made 1875
Character in Register Book.

Pressure of Steam 65 lbs. If Surveyed Afloat or in Dry Dock Albt. D. Dr. Classed 100 A 1
(State name of Dock.)

Registered Horse Power 400

Last Survey No. _____ Port L.M.C. 10.83 B.S. 7.85

Particulars of Repairs and Examination For Annual Survey

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Vessel placed in dry dock sea connections examined & found to be in good condition. One new propeller blade has been fitted. Tail shaft down nearly 3' in Stern bush. A new donkey boiler has been fitted on this occasion, particulars on annexed form.

General Observations, Opinion, and Recommendation:— *As far as seen of the machinery the vessel appears eligible to remain as classed.*


Office or Registration Fee (per Sec. 27)	£	:	:	} received by me, } 188
Survey Fee (per Section 28)	£	:	:	
Special Damage Fee (per Section 28)	£	:	:	
Certificate (if required)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	

Geo. E. Wilkinson
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRIDAY 8 JAN 1886

Committee's Minute

Assigned



Lloyd's Register Foundation
 LON676-0344

Insert Character of Ship and Machinery precisely as in the Register Book.