

REPORT of SURVEY for REPAIRS, &c.

46930*

No. 46930*

Port of

Received in London Office,

THURS 20 JAN 1887

No. in
Reg. Book.

Survey held at London

Date, First Survey

Last Survey

15th Jan

301 on the Iron Steamer "Albano"

(No. of Visits)

Master

YEAR.

MONTH

TONNAGE:-

NET

697

GROSS

1066

UNDER DK.

A15

Built at Hull

Owners T. Wilson & Sons.

By whom M. Samuelson & Co

When 1861

2nd

Port belonging to Hull

Owner's Address

(if not already recorded in Appendix to Register Book.)

If Surveyed Afloat or in Dry Dock Afloat Name of Dock Millwall Docks. Destined Voyage Hull.

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft.

ins.

(if these particulars are not yet recorded in the Register Book.)

Years assigned,
if a Wood Ship.

Character in
Register Book.

Last Survey, No. 8448

Port

Lon

Classed

B. 1.

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

in Summer

ft.

ins.

in Winter

ft.

ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Found in the after part of the main hold, the middle line keelson bent up about 6 inches, and several of the floors broken. The vessel has started for Hull, where it is intended to effect the necessary repairs.

Apart from the damage - the lower deck beam at the after end of the main hatchway, and its connection to the sides of the vessel are in my opinion unsatisfactory & require attention.

PRESENT CONDITION OF THE

Decks

Waterways

Comings

Up'r Dk. Beams & Fastenings

Low'r Dk. Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Engine Room Skylights

Plank (Bottom) & Counter

Treenails or Rivets

Breasthooks and Stemson

Transoms, Pointers, & Crutches

Timbers of Frame at the openings

Ditto ditto at other places

Keelsons

Clamps & Shelves

Ceiling

Rudder

Windlass & Capstan

Pumps

Cement (if Iron Ship)

Caulk'ng of Bot'm, D'k, & Watrways

Copper, or Y.M.

(State if on Felt.)

When put on

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers & Warps

Standing & Running Rigging

Hatches

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo & Main Hatchways

General Observations, Opinion as to Class, Recommendation, &c.:

It is submitted that the Surveyor at Hull be informed of this case as above stated

Entry Fee (if chargeable) per Scale I., Sec. 27...

£

Office Fee (if chargeable) per Scale II., Sec. 27...

£

Survey Fee (per Section 28)

£

Special on Damage, Fee (if any) (per Sec. 28)....

£

*Certificate (if required) to be sent as per margin

£

Travelling Expenses (if chargeable)

£

Second Surveyor's Fee (if any)

£

Fees

received by me,

188

J. H. Truscott, 2021

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned