

49849  
s & Boilers.  
TUE TO SEP 89

TUE TO SEP 05

497  
state if a Report is also now sent on the Ship  
on it not when and when one will be sent

© 2021

Lloyd's Register  
Foundation

LONG 687-0118



49849 Lon

be taken out & replaced with a stay & nut. That  
all caulking to the shell should be done the  
floor plates being removed for that purpose & that  
any minor repairs found to be necessary & beyond  
those stated above should be done.

In consequence of the age of the boiler it is  
recommended that the pressure in the main boiler  
be reduced to 60 lbs  $\square$  from 90  $\square$ , & that a pressure  
(hydraulic) of  $1\frac{1}{2}$  times the working pressure be put  
on the boiler as a test.

As all these recommendations have not been carried  
out a letter was sent to owner stating what was required  
before the vessel could be cleared (see letter dated 6.9.89) affixed

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

It is submitted that the vessel and its  
equipment have been thoroughly  
examined, and the work as  
above described, has been  
done to the satisfaction of  
the Surveyors.  
W. A.  
12-9-89.



© 2021

Lloyd's Register  
Foundation