

52575 Jan.

Loose rivets - in stem & stem ports - taken out & renewed
Repairs not due to damage

Buckled plate - on forecastle port-side, viz: 2nd strake from top
& 2nd plate from stem fixed in place. frame in way of
this has had a brace fitted between it & the plate & a
runner bar fitted as compensation. Three pillars in
fore hold straightened, sundry minor repairs done
Bottom cleaned & painted.

Francis Pulton