





52642. *Jan.*

*Starboard side were observed to be drawn in their counterstake and should be renewed, and the attention of the superintending Engineer was called to this and he promised to have it done. The rivets on the port side could not be seen (as that side was away from the quay), and should therefore be examined.*

*Chas H. Jordan*