

It is submitted that
this vessel is eligible to
remain ALL CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

On account of damage, a
few bolts have been fitted
to the cracks, and
repairs have been
done to the air &
circulating pumps.
The vessel is intended
to get new pumps
on the results
return in about
9 weeks time.

15/4/93



© 2019
Lloyd's Register
Foundation