

It is submitted that
this vessel is eligible to
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

On account of damage through
grounding the shafting & sea
connections have been examined,
a new thrust shaft has been
fitted & the shafting lined
up. Other repairs of moderate
extent have been done to
the machinery —
on account of wear the
the double boiler has
been repaired as
recommended in the ten
rept no 53706, & the
original pressure
of 70 lbs has
been restored —

20/9/29/5/93

[Faint, mostly illegible handwritten text in cursive script, likely bleed-through from the reverse side of the page.]

