

No. 54539

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office THURS. 15 JUN 1893)

Date of writing Report June 14 1893 When handed in at Local Office London is London Port of London  
No. in Reg. Book 760 Survey held at London Date First Survey and Last Survey June 14 1893  
on the Machinery of the Wood, Iron or Steel SS. MORAYSHIRE Master Coule  
Tonnage Gross 3822 Net 2481 Vessel built at Newcastle By whom Hawthorn Leslie & Co When 1890 Boilers, when made (Main) 1890 (Donkey) 1890  
Registered Horse Power 300 Engines made at Do When 1890 Owners Elderslie P.S. Co Ltd Port Glasgow Voyage Australia  
No. of Main Boilers two If Surveyed in Dry Dock Millwall Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).  
Steam Pressure in Main Boilers 160 lbs. in Donkey Boiler -

Last Survey No. Port Particulars of Examination and Repairs (if any) Condition

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Examined propeller, stern bush, & sea connections fastenings, all found to be in good condition

General Observations, Opinion, and Recommendation:— This vessel's machinery is now as far as seen in good condition & in my opinion the vessel is eligible to remain as classed without fresh record of survey.

Office or Registration Fee (per Sec. 27) £ : : Fees applied for  
Survey Fee (per Section 28) £ : :  
Special Damage Fee (per Section 28) £ : :  
Travelling Expenses (if chargeable) £ : :  
Received by me, £

\*State if Certificate is required

Committee's Minute TUES. 18 JUL 1893

Assigned as now

TUES. 30 JAN 1904

Engine Surveyor to Lloyd's Register of British and Foreign Shipping.

Lloyd's Register Foundation

LON699-0261



It is submitted that  
this vessel is eligible to  
remain AS CLASSED.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

15/7/93 -



© 2019

Lloyd's Register  
Foundation