

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report *Feb. 12 1894* When handed in at Local Office *13.2.94* is *Port of London.*

No. in Reg. Book *892* Survey held at *London.* Date, First Survey *Feb. 10* Last Survey *Feb. 12 1894*

on the Machinery of the ~~Wood Iron or Steel~~ *S.S. STARLING* Master *Wilson.*

Tonnage Gross *804* Net *454* Vessel built at *Newcastle* By whom *Patmos Co. (Lim)* When *1887* Boilers, when made (Main) *1887* (Donkey) *1887*.

Registered Horse Power *120* Engines made at *50* Owners *General Steam Nav. Co* Port *London.* Voyage *Coasting.*

No. of Main Boilers *1* Steam Pressure in Main Boilers *150 lbs* If Surveyed Afloat or in Dry Dock *G.S.N. Co's Wharf.* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boiler *50 lbs.* Last Survey No. *54886* Port *London*

Particulars of Examination and Repairs (if any) *B.S.*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *Yes*

Do. " Donkey " " " *Yes*

If this was not done, state for what reasons? *✓*

And what parts of the Boilers could not be thus thoroughly examined? *✓*

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *Yes.*

Did the Surveyor examine the Safety Valves of the Main Boiler? *not adjusted.*

At what pressure were they afterwards adjusted under steam? *Yes.*

Did the Surveyor examine the Safety Valves of Donkey Boiler? *not adjusted.*

To what pressure were they afterwards adjusted? *not adjusted.*

If the Survey is not complete state what arrangements have been made for its completion? *This vessel has now left this port for Manchester where facilities will be given to complete the survey. Examined Main and Donkey Boilers internally & externally & Safety Valves, all found to be in good condition, except the vertical stays of the donkey Boiler, which were found to be much worn.*

To complete the survey, the vertical stays of the Donkey boiler are to be renewed and all the safety valves are to be adjusted under steam.

General Observations, Opinion, and Recommendation:— *This vessel's boilers, with the above exception, are now in good condition & in my opinion the vessel is eligible to remain as classed with record **B.S. 2.94** when the survey has been completed.*

Office or Registration Fee (per Sec. 27) £ *1.10.0* Survey Fee (per Section 23) £ *1.10.0* Special Damage Fee (per Section 28) £ *23/2* Travelling Expenses (if chargeable) £ *14.2 1894*

State if Certificate is required _____ Committee's Minute *Deferred for completion of B.S. White Ship Rpt to Ship 16.12.94* Assigned *Pl. W. M. M. Salmon.* Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



Answer character of Ship and Machinery precisely as in the Register Book.

FRIDAY 4 JAN 1895

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

Waiter
per 58.
Deferred
Jan. at 4.1.95

FRI 17 MAY 1895

Ad. due
Deferred
Wife Jan.
at 7.5.95

FRI 1 OCT 1896

[Handwritten signature]

[Faint handwritten notes and scribbles in the center of the page]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS



© 2019
Lloyd's Register
Foundation