

Report of Survey for Repairs, &c., of Engines and Boilers.

13 APR 1894

Date of writing Report *April 17 1894* When handed in at Local Office *is* Port of *London*
 No. in Reg. Book. *333* Survey held at *London* Date, First Survey *March 24* Last Survey *April 17 1894*
 on the Machinery of the *Wood, Iron or Steel* *S.S. "GODIYA"* Master *Henderson*
 Tonnage { Gross *1366* Vessel built at *Middlebrook* By whom *Crags & Son* When *1882* YEAR. MONTH.
 Net *887* Engines made at *do* When *1882* Boilers, when made (Main) *1882* (Donkey) *1893*
 Registered Horse Power *115* Owners *Demerara & Barbice S. S. Co.* Port *London* Voyage *Demerara*
 No. of Main Boilers *1* If Surveyed Afloat or in Dry Dock *S.W. India Dry Dock*
 Steam Pressure in Main Boilers *Solls* (State name of Dock.) *& Wet Dock.*
 in Donkey Boiler *Solls* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. *B.S. 0* Port *B.S. 0*
 Particulars of Examination and Repairs (if any) *Condition.*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *Yes.*

Do. " Donkey " " *No.*

If this was not done, state for what reasons? *New Donkey Boiler now fitted.*

And what parts of the Boilers could not be thus thoroughly examined? *✓*

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *✓*

Did the Surveyor examine the Safety Valves of the Main Boiler? *Yes.*

At what pressure were they afterwards adjusted under steam? *Solls per sq.*

Did the Surveyor examine the Safety Valves of Donkey Boiler? *No.*

To what pressure were they afterwards adjusted? *Solls per sq.*

If the Survey is not complete state what arrangements have been made for its completion? *Completed.*

Examined Main Boiler internally & externally & Safety valves. all found to be in safe working condition.

The New Donkey Boiler has now been fitted on board & secured & all the necessary connections made.

The safety valves were afterwards adjusted under steam.

Examined propeller, stem bush, & sea connection fastenings in dry dock, all found to be in good condition.

For particulars of New Donkey Boiler see London report N° 54974.

General Observations, Opinion, and Recommendation:— *This vessel's boilers are now in good condition & in my opinion the vessel is eligible to remain as classed with record B.S. 4. 94*
 (State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey; thus, for example, B.S. 9.92, B.&M.S. 9.92 or L.M.C. 9.92, as the case may be.)

Office or Registration Fee (per Sec. 27) £ : :
 Survey Fee (per Section 28) £ *1* : *10* : *0*
 Special Damage Fee (per Section 28) £ : :
 Travelling Expenses (if chargeable) £ : :

Fees applied for

18/4/1894

Received by me,

9/5/1894

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute

Assigned

B.S. 4. 94

FRI 20 APR 1894



© 2019

Lloyd's Register Foundation

LON701-0466

State if a Report is now sent on the Ship or if not whether, and when, one will be sent.

*Certificate to be sent to

14-LRPH-Form No. 9-Transfer Ink-5,000, 2/10/93.
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character of Ship and Machinery precisely as in the Register Book.

It is submitted that
this vessel is eligible for
THE RECORD

B-5-4-94

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

On 1st of Jan I wear
a new dark blue
jacket.

N.A.

18-4-94

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation