

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 20th Aug 94 When handed in at Local Office 18

Port of London.

No. in Survey held at London.

Date, First Survey June 29, Last Survey 20th Aug 1894

82 on the Wood Iron or Steel S.S. "Warrnambool"

Master J. H. Ekris.

TONNAGE:-

GROSS 3513

UNDER DECK 3213

NET 2213

Built at Sunderland

By whom Sunderland S.B. Co.

When 1892 8

OWNERS W. Lund.

Port belonging to London.

OWNERS' Address

(If not already recorded in Appendix to Register Book.)

Surveyed Afloat in Dry Dock? Both.

Name of Dock S.W. I. dyke

Destined Voyage Australia

WB=DBa

tons; f

tons; uE&B

tons; CellDB

tons;

FPT

tons; APT

tons; MT

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Survey, No. 54873 Port London

CHARACTER.

* for Special Survey, Date of last Survey and of Periodical Surveys.

Year assigned now expired.

Machinery and Boiler Surveys (including date of N.B., if any).

100 A1.

6.93.

LM.C. 8.92.

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition & Insulation of No. 1 & 2 holds.

Vessel placed in dry dock - bottom cleaned, examined & repainted. Chain cables ranged & examined. Previous to insulation, the floors, frames, keelsons, and all iron work in No. 1 & 2 holds were examined & found in good order. Three additional quarter pillars were fitted on port side at after end of No. 2 hold under the Refrigerating machinery - the pillars being fitted from tank top to Tween dk beams. No. 1 & 2 Tanks tested under water pressure & found tight.

SUMMARY OF DAMAGE REPAIRS: - Plates, Faired or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs.

PRESENT CONDITION OF THE

Decks

Waterways

Coamings

Up'r Dk. Beams & Fastenings

Low'r Dk. Beams & Fastenings

Plating

Decking

Rivets or Rivets

Breasthooks & Stemson

Transoms, Pointers, & Crutches.

Frames of Frame at the openings.

ditto ditto at other places.

Keelsons

Clamps, Shelves & Stringers

Selling

(State if examined.)

Ceiling

Cement or Asphalt

(State which.)

Tanks

(State if now tested.)

Caulking of Bot'm, D'k, & Wat'rw'ys.

Copper, or Y.M.

(State if on Felt.)

When put on, Month

Rudder

Windlass & Capstan

Pumps

Engine Room Skylights

Coal Bunker, Open'gs, Lids, &c.

Scuppers

Cargo & Main H'tch'w'ys.

Hatches

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

length

Rule length

Hawsers & Warps

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel is now in a good and efficient condition and eligible in our opinion to remain as classed with record of survey 8.94.

Office Fee (if chargeable) per Scale II., Sec. 2

Survey Fee (per Section 25)

Special Damage or Repair Fee (if any) (per Sec. 25.)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Is Certificate now required?

Fees applied for,

22/8/18.94

Received by me,

28/8/18.94

26

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRIDAY 24 AUG 1894

100A1



© 2019

Lloyd's Register

Foundation

LON 703 - 0059