

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

23 MAR 95

Date of writing Report *March 22* 18*95* When handed in at Local Office *London* Port of *London*
 No. in Reg. Book. *66* Survey held at *London* Date, First Survey *Feb. 22* Last Survey *March 22 1895*
 on the Machinery of the *Wood, Iron or Steel* *S.S. ECHUCA* Master *Bond*
 Tonnage { Gross *2826* Net *1736* Vessel built at *Middlesbrough* By whom *A. Dixon & Co.* When *1889* YEAR. MONTH.
 Registered Horse Power *450* Engines made at *Hartlepool* When *1889* Boilers, when made (Main) *1889* (Donkey) *1889*
 No. of Main Boilers *3* Owners *W. Lund* Port *London* Voyage *Australia*
 No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Victoria St. S.W. 1.8.95* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 Steam Pressure in Main Boilers *150 lbs.* (State name of Dock.) *Dry Dock*
 in Donkey Boilers *80 lbs.*

Last Survey No. *Port*Particulars of Examination and Repairs (if any) *B.S.*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Examined Main & Donkey Boilers internally & externally and safety valves, also propeller, stem bush, & sea connections fastenings, all found to be in good condition.

The safety valves were afterwards adjusted under steam.

General Observations, Opinion, and Recommendation:— *This vessel's Boilers & Machinery as far as seen are now in good condition & in our opinion the vessel is eligible for record B.S. 3.95*

Office or Registration Fee (per Sec. 27) £ *2 10 0*
 Survey Fee (per Section 28) £ *2 10 0*
 Special Damage Fee (per Section 28) £ *2 5 0*
 Travelling Expenses (if chargeable) £ *2 5 0*

Fees applied for

23 3 18 25

Received by me,

2/4/95

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute

Assigned

TUES. 26 MAR 1895



© 2019

Lloyd's Register Foundation

W0704-0453

State if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

*Certificate to be sent to

16-LRPB—Form No. 9—Transfer Ink—4,000, 25/9/94.

Insert Character of Ship and Machinery precisely as in the Register Book.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD B.S. 3-95

M.A.
23. 3. 95

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation