

Report of Survey for Repairs, &c., of Engines and Boilers.

TUES 14 MAY 1895

Date of writing Report 13th May 95 When handed in at Local Office 18 Port of London

No. in Reg. Book. 17 Survey held at London Date, First Survey 1st May Last Survey 7th May 1895

on the Machinery of the Wood, Iron or Steel S.S. "Nairnshire" Master Olsen

Tonnage { Gross 3720 Net 2428 Vessel built at Newcastle By whom L. W. Hawthorn Leslie & Co When 1889 Boilers, when made (Main) 1889 (Donkey) 1889

Registered Horse Power 306 Engines made at Do. Owners J Turnbull, Martin & Co Port Glasgow Voyage Australia

No. of Main Boilers Two No. of Donkey Boilers one Steam Pressure in Main Boilers 160 in Donkey Boilers 90

If Surveyed Afloat or in Dry Dock James I. Wks. Dry Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. Port Particulars of Examination and Repairs (if any) Condition

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " " " No

If this was not done, state for what reasons? Not due for survey.

And what parts of the Boilers could not be thus thoroughly examined? ✓

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? ✓

Did the Surveyor examine the Safety Valves of the Main Boiler? No

At what pressure were they afterwards adjusted under steam? Not adjusted

Did the Surveyor examine the Safety Valves of Donkey Boiler? No

To what pressure were they afterwards adjusted? Not adjusted

If the Survey is not complete state what arrangements have been made for its completion? Complete.

Propeller & sea-connection fastenings examined & found in order.

General Observations, Opinion, and Recommendation:— This vessel's machinery, so far as seen, is in safe working condition and eligible, in my opinion, to remain as classed without further record of survey.

Office or Registration Fee (per Sec. 27).....	£	:	:	Fees applied for
Survey Fee (per Section 28).....	£	:	:	18
Special Damage Fee (per Section 28).....	£	:	:	
Travelling Expenses (if chargeable).....	£	:	:	Received by me,
				18

R. Elliott
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

* State if Certificate is required FRI 24 MAY 1895
Committee's Minute Assigned as now

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain as CLASSED.

M.A.
23-5-95

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation