

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor creases and discoloration, characteristic of old paper. The left edge of the page is bound into a dark, possibly black or dark brown, inner cover material. The overall lighting is even, highlighting the subtle variations in the paper's tone.



An account of Damage. Storm bulk &  
propeller renewed, new outer liner fitted  
on screw shaft.

It is submitted that  
this vessel is eligible to  
remain AS CLASSED.

Mrs.  
23.9.95

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to shew through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation