

Iron Ship "Niobe"

(1). The deck is defective in places round the hatchways and there are a large number of graving pieces in it. The deck requires to be bored and examined and graving pieces in deck removed for examination in way of same.

(2). The ceiling is worn and defective in places & requires to be part renewed and put in good order.

(3). The upper part of the fore peak to be scaled & painted.

The above items remain to be done to complete the S.S. No. 2.

The vessel leaves this port ^{in ballast.} for her home port - Aberdeen and it is stated that the survey will be complete and the necessary repairs done upon her arrival there under the inspection of the Society's Surveyor.

E. B. Champness