

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

THUR 29 OCT 1896

Date of writing Report *27th Oct 1896* When handed in at Local Office *27th Oct 1896* Port of *London*

No. in Reg. Book *772* Survey held at *London* Date, First Survey *22nd Oct 1896* Last Survey *26th Oct 1896*

on the Machinery of the *Wood, Iron or Steel* *S.T. Bangalore* Master *F. Blower*

Tonnage Gross *2990* Net *1875* Vessel built at *Newcastle* By whom *W. & A. Pirbright & Co* When *1889* 9

Registered Horse Power *420* Engines made at *"* When *89* Boilers, when made (Main) *89* (Donkey) *89*

No. of Main Boilers *2* Owners *R. Lund* Port *London* Voyage *Melbourne*

No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Afloat in India Dry Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. _____ Port _____

Particulars of Examination and Repairs (if any) *In Dry Dock. ± 100 H. 1.96. + L.M.C. 1.94.*

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Do. " Donkey " "

If this was not done, state for what reasons? *not under survey*

And what parts of the Boilers could not be thus thoroughly examined? *not done*

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? *no*

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? *no*

To what pressure were they afterwards adjusted? *no*

Has the propeller shaft been drawn and examined at this time? *no*

If the Survey is not complete state what arrangements have been made for its completion? *Complete.*

Propeller stem-bush and outside fastenings of the sea connections examined and found in good order.

This vessel's Donkey Boiler repairs are due for survey in Dec next. Please see Limitation List - It is proposed by Owners that this survey be postponed until the vessel next returns to the U.K. probably in February next. In my opinion the Donkey Boiler is still in efficient condition and the above proposal is respectfully submitted for the Committee's favourable consideration.

General Observations, Opinion, and Recommendation :-

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,95, B.&M.S. 9,95 or L.M.C. 9,95, 140 lb., F.D., &c.)
The machinery of this vessel is in good condition and in my opinion eligible to remain as classed without fresh record, but with alteration of date in Limitation List to 2.99.

	£	s	d	Fees applied for
Office or Registration Fee (per Sec. 27)				18
Survey Fee (per Section 28)				
Special Damage Fee (per Section 28)				
Travelling Expenses (if chargeable)				18
Received by me,				

J. Ritchie
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.


*State if Certificate is required _____
Committee's Minute *TUES 3 NOV 1896*

Assigned *As now subject J.H.*

Has a Survey also been held on Ship? If so, is the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book.

*Certificate to be sent to



LON 710-0499

*It is submitted that
this vessel is eligible to
remain AS CLASSED, subject
to the Donkey boiler uptakes
being again examined
before the end of Feb. 97.*

*R. E.
29/10/96.*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2020

Lloyd's Register
Foundation