

Report of Survey held at London Port of London
Date, First Survey 15th June Last Survey 24th June 1897
(No. of Visits) 2 Master J. Mayors
Surveyed on the Wood, Iron or Steel S.S. Tongariro
TONNAGE:- Built at Glasgow By whom J. Elder & Co. When 1883 8
GROSS 4163 Owners New Zealand S. Co. (Lim) Port belonging to London
UNDER DECK 2854 Owners' Address _____
NET 2657 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Quilem Destined Voyage _____
WB=CellDBorDBa _____ feet; uE&B _____ feet; f _____ feet; }
total capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. 1-100 A1 Span deck 5.95 S.S. Im. M2-92
Date of last Survey and of Periodical Surveys. 1. 2m. C 4.96
Machinery and Boiler Surveys (including date of N.B., if any).
Society's Freeboard (if assigned) as painted on Ship and now verified } 9 ft. 0 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage repair

An indented plate on the starboard bow has now been taken off the frames in way of same faired & repaired; beam knees expanded the plate faired & re-riveted in place & all shell work made good
Nothing further done to complete S.S. No. 3, but the owners propose to complete this survey on the vessel's return.

SUMMARY OF DAMAGE REPAIRS :—		Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed									
Faired or Repaired ...									
PRESENT CONDITION OF THE		Frames of Frame at the openings				Rudder	Hatches		
Ditto ditto at other places		Windlass & Capstan				Boats			
Keelsons		Have Pumps now been examined and found efficient?				Masts, Yards, &c.			
Stringers, Clamps & Shells		Have Sluice Valves now been examined and found efficient?				Condition, how ascertained			
Salting		Have Watertight Doors now been examined and found efficient?				(State if wedges removed)			
(State if examined.)		Dblg. Plates under Sounding Pipes				Sails			
Ceiling		Engine Room Skylights				Equipment letter			
Cement or Asphalt		Coal Bunker, Open'gs, Lids, &c.				Anchors, No. of			
(State which.)		Scuppers				Cables (State if now ranged)			
Tanks		Cargo & Main H'tch'w'ys				" length			
(State if now tested.)						(on board)			
Caulking of Bot'm, D'k, & Wat'rw'ys						" Rule length			
Copper, or Y.M.						(per Table 22)			
(State if on Felt.)						Hawsers & Warps			
When put on, Month						Standing & Running Rigging			
Year									

General Observations, Opinion as to Class, Recommendation, &c. :-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,97," or "to remain as classed and to have record of survey, 1,97, and the notations of ss No. 1-97 and ptND97, &c."

This vessel appears to be in good condition & is eligible in my opinion to remain as classed with record of survey &c.

Fees applied for, _____
Received by me, _____
Surveyor to Lloyd's Register of British & Foreign Shipping.
FRI, 9 JUL 1897
FRI, 29 OCT 1897
TUES, 9 AUG 1898
TUES, 14 DEC 1897
Lloyd's Register Foundation