

Two new screw shafts fitted, cause not stated.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that this vessel is eligible to remain as **CLASSED**.

✓ to be removed from the Limit List.

W.S.
21.9.97

[Faint, illegible handwritten notes in the main body of the page, possibly bleed-through from the reverse side.]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.