

59433. Jan

Continued

Repairs of damage by grounding:-

Bottom examined in dry dock, tanks cleaned out, ceiling lifted; cement floors frames &c examined and found to be uninjured. A few butts of bottom plating restopped and rudder stop renewed.

E. J. Milton.
Capt. Cooper

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation