

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

Date of writing Report 18 When handed in at Local Office 18 Port of London

No. in Reg. Book. Survey held at Alexandria Date, First Survey Last Survey 18

212 on the Machinery of the Wood, Iron or Steel SS "Electra" Master H. Smith

Gross 1219 Net 656 Vessel built at By whom R. Napier & Sons When 1885 Jan

Registered Horse Power 220 Engines made at When 1885 Boilers, when made (Main) 1885 (Donkey) 1885

No. of Main Boilers 2 Owners Eastern Tel. Co. Ltd. Port Lon Voyage

No. of Donkey Boilers 2 If Surveyed Afloat or in Dry Dock (State name of Dock.)

Steam Pressure in Main Boilers 85 in Donkey Boilers 65

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. 58487 Port Lon

Particulars of Examination and Repairs (if any)

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

CHARACTER.	Years Allowed now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
* 100 A1		* L.M.C. 996
Long dk with freeboard		
197		
S.S. No. 3 12-96		

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time? If spare propeller shaft fitted, state whether new?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,95, B.&M.S. 9,95 or L.M.C. 9,95, 140 lb., F.D., &c.)

Registration Fee (per Sec. 27) £ : : Fees applied for

10 (per Section 28) £ : : 18

Damage Fee (per Section 28) £ : : Received by me,

ing Expenses (if chargeable) £ : : 18

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

If Certificate is required

Committee's Minute TUES. 22 FEB 1893 FRI. 18 MAR 1893

Assigned Deferred for completion of B.S. Write own.

Lloyd's Register Foundation LON 714-0433