

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

TUES. 24 MAY 1893

Date of writing Report *21st May* 18 *98* When handed in at Local Office *23rd May* 18 *98* Port of *London*
 No. in Reg. Book. *242* Survey held at *London* Date, First Survey *11th May* Last Survey *24th May 1898*
 on the Machinery of the *Wood, Iron or Steel* *J. T. Widgeon* Master *Hurst*
 Tonnage { Gross *601* Net *402* Vessel built at *N. Cle.* By whom *C. Mitchell & Co.* When *1876* 3.
 Registered { Horse Power *157* Engines made at *"* When *76* Boilers, when made (Main) *92* (Donkey) *92*
 No. of Main Boilers *2* Owners *Gen. Steam Navigation Co.* Port *London* Voyage *Breite*
 No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Afloat at Deptford Works.* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 Steam Pressure— in Main Boilers *70 lb* in Donkey Boilers *70.*

Last Survey No. *59838* Port *Lon*Particulars of Examination and Repairs (if any) *B. S.*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

in London All Safety Valves to adjust under steam
Now done! - Main Boiler examined throughout; same found to be generally in good order
Donkey Boiler examined throughout; same found to be now in Satisfactory Condition.

No opportunity given at this survey to adjust Safety Valves.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,95, B.&M.S. 9,95 or L.M.C. 9,95, 140 lb. F.D., &c.)

The Machinery of this vessel so far as now seen, is in good order and in my opinion eligible to remain as classed. The fresh record of B.S.-5-98 the deferred part this survey is completed.

Office or Registration Fee (per Sec. 27) £ :

Fees applied for

Survey Fee (per Section 28) £ *2* :*24/5* 18 *98*

Special Damage Fee (per Section 28) £ :

Received by me, *D. Ritchie*Travelling Expenses (if chargeable) £ *1* : *16* :*18*

*State if Certificate is required


Committee's Minute

Assigned

FRI. 27 MAY 1893

TUES. 14 JUN 1893

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019
 Lloyd's Register
 Foundation

LON 715-0347

B. I. due 10, 98 to be completed on vessel

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

return.

It is submitted that this vessel WILL BE eligible for the record.

B. I. 5/98 when all

lights & valves have been adjusted under steam

LL
24/5/98

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation