

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 24th May 1898 When handed in at Local Office 18 Port of London
No. in Survey held at London Date, First Survey 7th May 1898 Last Survey 21st May 1898
Reg. Book. 1067 on the Wood, Iron or Steel 88 " Australasian " Master By whom R Napier & Son
TONNAGE:— Built at Glasgow By whom R Napier & Son When 1884 YEAR. MONTH.
GROSS 2682 Owners G Thompson & Co Port belonging to Aberdeen
UNDER DEK 2516 Owners' Address _____
NET 1233 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock 1 Name of Dock Albert Dock Destined Voyage _____
WB=CellDBorDBa _____ feet; uE&B _____ feet; I _____ feet; }
total capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ tons. }
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 5948 Port Lon
(Periodical Surveys, when held, must be reported in detail and serialim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size, and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition

The bottom has been examined in dry dock, cleaned & coated. The rudder has been brushed.
Two small deck houses have been fitted forward, as companion to 3^d class passenger accommodation.

SUMMARY OF DAMAGE REPAIRS :—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed	...								
Removed and Faired or Repaired	...								
Faired or Repaired in place	...								

PRESENT CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblng. Plates under Sounding Pipes	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Souppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Treenails	Breasthooks & Stemson	Transoms, Pointers, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shelves	Salting	Copper, or Y.M. (State if on Felt.)	When put on, Month	Year	Boats	Masts, Yards, &c.	Condition, how ascertained	(State if wedges removed	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length (on board)	Rule length (per Table 22)	Hawsers & Warps	Standing & Running Rigging			
Decks	good						good						good																good		from 84	no	good	X	6	no				good			
Caulking of Decks																																											
Waterways																																											
Coamings																																											
Beams & Fastenings																																											
Outside Plating	good																																										
Caulking of ditto																																											
Rivets																																											
Breasthooks & Crutches																																											
Transoms																																											
Frames																																											
Reverse Frames																																											
Floors																																											
Keelsons																																											

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey.” “to remain as classed and to have record of survey, 1,98,” or “to remain as classed and to have record of survey, 1,98, and the notations of cs No. 1-98 and ptND98, &c.”
This vessel now appears to be in good & efficient condition & is eligible in my opinion to remain as classed with record of survey 5.98

Office Fee (if chargeable) per Scale II., Sec. 27	£	:	:	Fees applied for,
Survey Fee (per Section 28)	£	:	:	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute
Character assigned 100 A1
Spar deck BS 1.98
FRI 27 MAY 1898
Lloyd's Register Foundation
CONF 15-0351