



60119 Long

floor plates within the peak have been reinforced by fitting thwartship angles on their free edges. Also two of the deep floor plates above the tube have been extended downwards, the new part being connected to the old by thwartship tee bar joint pieces; and a similar reinforcing tee plate has been fitted above the tank top at the after end, across from frame to frame. In the riveting work, all holes were broached out to take rivets of a larger size.

C.P.A.

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register Foundation