

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 29th Aug 1898 When handed in at Local Office 18th Aug 1898 Port of London
 No. in Reg. Book 335 Survey held at London Date, First Survey 19th Aug 1894 Last Survey 25th Aug 1898
on the Wood, Iron or Steel 88 "Winifreda" (No. of Visits 4) Master W. J. W. W.
 TONNAGE:- Built at Belfast By whom Harland & Wolff When 1898 MONTH 2
 GROSS 6833 Owners Atlantic Transport Co Port belonging to Liverpool
 UNDER DEK. 6052 Owners' Address (if not already recorded in Appendix to Register Book.)
 NET 4423

Surveyed Afloat or in Dry Dock? Albert Name of Dock Albert Destined Voyage

WB=CellDBorDBa feet; uE&B feet; J feet; }
 total capacity tons; FPT tons; APT tons; MT feet tons. }
 N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4816 Port Bel

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER.
 * for Special Survey.
 Date of last Survey and of Periodical Surveys.
 Years since last survey.
 Machinery and Boiler Surveys (including date of N.B., if any).
 * 100A1
 2.98
 * LMC 2.98

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Insulation

The forward part of No. 5 Upper 'tween decks and the whole of No. 5 lower 'tween Decks have now been insulated. Before covering up the steel work it was thoroughly cleaned & the coating found to be in good condition. A freezing engine (carbonic anhydride principle) has been on the upper deck, over the insulated spaces.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks <u>good</u>	Stringers <u>good</u>	Engine Room Skylights <u>good</u>	Boats <u>good</u>
Caulking of Decks <u>"</u>	Inner Bottom Plating <u>"</u>	Coal Bunkers, Open'gs, Lids, &c. <u>"</u>	Masts, Yards, &c. <u>"</u>
Waterways <u>"</u>	State if Tanks now tested. <u>"</u>	Scuppers <u>"</u>	Condition, how ascertained <u>from Dts</u>
Coamings <u>"</u>	Bulkheads <u>"</u>	Cargo Hatchways <u>"</u>	(State if wedges removed <u>no</u>)
Beams & Fastenings <u>"</u>	Ceiling <u>"</u>	Hatches <u>"</u>	Sails <u>"</u>
Outside Plating <u>"</u>	Cement or Asphalt. (State which.) <u>"</u>	Planking of Wood Vessels <u>"</u>	Equipment letter <u>ct</u>
Caulking of ditto <u>"</u>	Rudder <u>"</u>	Treenails ditto <u>"</u>	Anchors, No. of <u>6</u>
Rivets <u>"</u>	Windlass <u>good</u>	Breasthooks & Stemson ditto <u>"</u>	Cables (State if now ranged) <u>no</u>
Breasthooks & Crutches <u>"</u>	Have Pumps new been examined and found efficient? <u>"</u>	Transoms, Pointers, & Crutches ditto <u>"</u>	" length (on board) <u>"</u> size <u>"</u>
Transoms <u>"</u>	Have Sluice Valves now been examined and found efficient? <u>"</u>	Timbers of Frame at openings ditto <u>"</u>	" Rule length (per Table 22) <u>"</u> size <u>"</u>
Frames <u>good</u>	Have Watertight Doors now been examined and found efficient? <u>"</u>	Ditto ditto at other places ditto <u>"</u>	Hawsers & Warps <u>good</u>
Reverse Frames <u>"</u>	Dblng. Plates under Sounding Pipes <u>"</u>	Stringers, Clamps & Shells ditto <u>"</u>	Standing & Running Rigging <u>"</u>
Floors <u>"</u>		Salting (State if examined.) ditto <u>"</u>	
Kelsons <u>"</u>		Copper, or Y.M. (State if on Fell.) ditto <u>"</u>	
		When put on, Month <u>"</u> Year <u>"</u>	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel now appears to be in good condition & is eligible in my opinion to remain as classed with record of survey 8.98. and also of Ref. Mch.

Office Fee (if chargeable) per Scale II., Sec. 27£

Survey Fee (per Section 28)£

Special Damage or Repair Fee (if any) (per Sec. 28.)£

Travelling Expenses (if chargeable)£

Second Surveyor's Fee (if any)£

Fees applied for,

18

Received by me,

18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI. 2 SEP 1893

100A1

Ref. Mch. J. H. J.



© 2019

Lloyd's Register Foundation

LON716-0277