





60 3574 Jan

The floor plates in the tank under the boilers, are wasted thin, it is proposed to make the necessary repairs on the vessel's return.

To complete the survey the following remains to be done:—

To examine the fore peak, the upper part of after peak, all tanks of double bottom excepting No. 3, all bunkers excepting the forward cross bunker, the Machinery luges, <sup>lugs of A.B.</sup> ~~tanks~~ No. 4 hold. The upper deck, Cable slivers & WT doors. To test all tanks excepting Nos 1 & 3 of double bottom. To repair the tank floor under boilers and verify the foreward A.B.

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.