

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18. When handed in at Local Office 18. Port of London
No. in Reg. Book. 506 Survey held at London Dry Dock Date, First Survey 25th Oct Last Survey 27th Oct 1898
on the Wood, Iron or Steel & Met Bl^d Lock Torridon Master three

TONNAGE:— Built at Glasgow By whom Barclay Curle & Co When 1881. 11
GROSS 2081 Owners General Shipping Co Port belonging to Glasgow
UNDER DEK. 1931 Owners' Address
NET 2000 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock London D. D. Destined Voyage
WB=CellDBorDBa feet; uE&B feet; J feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 753 Port Mel
CHARACTER.
* for Special Survey.
Date of last Survey and of Periodical Surveys.
Machinery and Boiler Surveys (including date of N.B., if any).
S.S. 100A1
S.S. Nov 3. 4. 94
S.S. Nov 1. 98
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition.

Vessel placed in dry dock, bottom examined cleaned and coated.

SUMMARY OF DAMAGE REPAIRS:—		Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed	...								
Removed and Faird or Repaired	...								
Faird or Repaired in place	...								
PRESENT CONDITION OF THE		<u>Good</u>							
Decks		Stringers				Engine Room Skylights			Boats
Caulking of Decks		Inner Bottom Plating				Caulking, Open'gs, Lids, &c.			Masts, Yards, &c.
Waterways		State if Tanks now tested				Scuppers			Condition, how ascertained
Coamings		Bulkheads				Cargo Hatchways			(State if wedges removed)
Beams & Fastenings		Ceiling				Hatches			Sails
Outside Plating		Cement on top of (State which.)				Planking of Wood Vessels			Equipment letter
Caulking of ditto		Rudder				Treenails ditto			Anchors, No. of
Rivets		Windlass				Breasthooks & Stemson ditto			Cables (State if now ranged)
Breasthooks & Crutches		Have Pumps now been examined and found efficient?				Transoms, Pointers, & Crutches ditto			" length (on board) size
Transoms		Have Sluice Valves now been examined and found efficient?				Timbers of Frame at openings ditto			" Rule length (per Table 22) size
Frames		Have Watertight Doors now been examined and found efficient?				Ditto ditto at other places ditto			Hawsers & Warps
Reverse Frames						Stringers, Clamps & Shelves ditto			Standing & Running Riggings
Floors						Salting (State if examined.) ditto			
Keelsons						Copper, or Y.M. (State if on felt.) ditto			
		Dblng. Plates under Sounding Pipes				When put on, Month Year			

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."
This vessel being now in a good & efficient condition is eligible in my opinion to remain as classed with record of survey 10-98.

Office Fee (if chargeable) per Scale II., Sec. 27	£	:	:	Fees applied for,
Survey Fee (per Section 28)	£	:	:	18.
Special Damage or Repair Fee (if any) (per Sec. 28.)	£	:	:	Received by me,
Travelling Expenses (if chargeable)	£	:	:	18.
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute
Character assigned
FRI, 4 NOV 1898
100A1

T. Shilstone
Surveyor to Lloyd's Register of British & Foreign Shipping.