

REPORT of SURVEY for REPAIRS, &c.

Date of Writing Report 11-11-98 When handed in at Local Office 11-11-98 Port of London
 No. in Survey held at London Date, First Survey 10-11-98 Last Survey 11-11-1898
 Reg. Book. 1136 on the ~~Wood, Iron~~ Steel s/s Strathairly Master Henderson 98
 TONNAGE:— Built at Greenock By whom Russell & Co When 1894-6
 GROSS 4142 Owners Burrill & Co Port belonging to Glasgow
 UNDER DECK 3909 Owners' Address
 NET 2704 (if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock Dry Dock Name of Dock Milnevale Dk Destined Voyage New York
 WB=CellDBorDBa feet; uE&B feet; 1 feet; }
 total capacity tons. FPT tons; APT tons; MT feet tons. }
 N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 35798 Port London Nwe.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. Date of last Survey and of Periodical Surveys. Years Assigned now or previously. Machinery and Boiler Surveys (including date of N.B., if any).

+100 AI, 12-97
+2 July 6.94

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition. Part 8. 8 nos.

This steamer was seen in the Milnevale Dry Dock the bottom examined cleaned and recoated this examination may be accepted as part of the Special Survey now due in June last. Notice was given to the Marine Superintendent that this survey was now due and was informed that owing to the vessel being urgently required, nothing could be done at the present moment, but that it would not be neglected & would be held at the first opportunity.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								
PRESENT CONDITION OF THE	Good	Good	Good	Good	Good	Good	Good	Good
Decks								
Caulking of Decks								
Waterways								
Coamings								
Beams & Fastenings								
Outside Plating								
Caulking of ditto								
Rivets								
Breasthooks & Crutches								
Transoms								
Frames								
Reverse Frames								
Floors								
Keelsons								
Stringers								
Inner Bottom Plating								
State if Tanks now tested								
Bulkheads								
Ceiling								
Cement or Asphalte								
Rudder								
Windlass								
Have Pumps now been examined and found efficient?								
Have Sluice Valves now been examined and found efficient?								
Have Watertight Doors now been examined and found efficient?								
Dblng. Plates under Sounding Pipes								
Engine Room Skylights								
Coal Bunkers, Open'gs, Lids, &c.								
Scuppers								
Cargo Hatchways								
Hatches								
Planking of Wood Vessels								
Treenails ditto								
Breasthooks & Stemson ditto								
Transoms, Pointers, & Crutches ditto								
Timbers of Frame at openings ditto								
Ditto ditto at other places ditto								
Stringers, Clamps & Shelves ditto								
Salting (State if examined.) ditto								
Copper, or Y.M. (State if on felt.) ditto								
When put on, Month Year								
Boats								
Masts, Yards, &c.								
Condition, how ascertained								
(State if wedges removed)								
Sails								
Equipment letter								
Anchors, No. of								
Cables (State if now ranged)								
Length size								
Staked complete								
Hawsers & Warps								
Standing & Running Rigging								

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This steamer now appears to be in good condition eligible in my opinion to remain as classed without a fresh record of survey 11-11-98

Office Fee (if chargeable) per Scale II., Sec. 27 £ : : Fees applied for, Edward Jno. Tierney
 Survey Fee (per Section 28) £ : : 18.
 Special Damage or Repair Fee (if any) £ : :
 Travelling Expenses (if chargeable) £ : :
 Second Surveyor's Fee (if any) £ : :
 Received by me, 18.
 Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
 Character assigned

TUES. 15 NOV 1898

TUES. 7 FEB 1899

TUES. 2 MAR 1899

TUES. 2 MAY 1899

Lloyd's Register
 Foundation

LON 717-0042