



60524 Ln

Four frames part renewed. Main deck stringer plate repaired. Lower deck gunwale bar part renewed

One hold stringer between web frames, out fained & replaced.

Hold beam in stokehold fained in place & bracket plate fained & replaced. One upper deck beam end fained in place, and some minor repairs to rail etc.

The bottom has been examined in dry dock & found in good condition.

A. Campbell Helms.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register Foundation