



Screw shaft examined  
Thrust block repaired, and  
slight repairs due to damage  
by grounding now effected.  
Propeller now renewed by Crowl

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that  
this vessel is eligible to  
remain as CLASSED.

A.C.H.

19.12.98.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation