

^{found}
Screw shaft, not a good fit in propeller.

A new Screw Shaft and propeller

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

now fitted
Stem bush relined.

It is submitted that
this vessel is eligible to
remain as **CLASSED**.

The above to be counted
as part S.S. Dec 5. 99.

to be completed in
London in May 99.

A.C.H.

2.1.99.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation