



Engines & Boilers examined  
Screw Shaft examined, New Spare Screw Shaft  
A new length of tunnel shafting now fitted.  
I.P. Slide face renewed.  
Slight Repair to Donkey Boiler

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that  
this vessel is eligible for  
THE RECORD. ✱ L.M.C. 12.98.

A.C.H.

7.1.99.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation