

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 21st Feb 1899 When handed in at Local Office 18 Port of London
No. in Survey held at 31 Gilbray Date, First Survey 15th Feb 3 Last Survey 20th Feb 1899
Reg. Book on the Wood, Iron or Steel 88 Mesaba Master
(No. of Visits)

TONNAGE:— Built at Belfast By whom Harland & Wolff When 1898 2
GROSS 6833 Owners Atlantic Transport Co. Ltd. Port belonging to Singapore
UNDER DEK 6052
NET 4423 Owners' Address
(If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Name of Dock Gilbray Destined Voyage
WB=CellDBoDBa feet; uE&B feet; I feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 60624 Port Pau

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR Addition of Bidge keels

The bottom has been examined in dry dock, cleaned and coated.
Bidge keels have now been fitted, about 200 feet in length, composed of 12 inch bulb bar and large double angles.

SUMMARY OF DAMAGE REPAIRS :—				Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :—
Renewed											
Removed and Fairied or Repaired											
Fairied or Repaired in place											

PRESENT CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt. (State which.)	Rudder	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblng. Plates under Sounding Pipes.	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways.	Hatches	Planking of Wood Vessels.	Treenails	Breasthooks & Stemson	Transoms, Pointers, & Crutches	Timbers of Frame at openings	Ditto ditto at other places	Stringers, Clamps & Shells	Salting	Copper, or Y.M. (State if on Felt.)	When put on, Month	Year	Boats	Masts, Yards, &c.	Condition, how ascertained	(State if wedges removed)	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	„ length (on board)	„ Rule length (per Table 22)	Hawsers & Warps	Standing & Running Rigging					
Decks	good						good						good																good			from Dk													
Caulking of Decks	"																																												
Waterways	"																																												
Coamings	"																																												
Beams & Fastenings	"																																												
Outside Plating	"																																												
Caulking of ditto	"																																												
Rivets	"																																												
Breasthooks & Crutches	✓																																												
Transoms	✓																																												
Frames	"																																												
Reverse Frames	"																																												
Floors	✓																																												
Keelsons	✓																																												

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,98,” or “to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c.”

This vessel now appears to be in good condition and is eligible in my opinion to remain as classed with record of survey 2.99

Office Fee (if chargeable) per Scale II., Sec. 27£
Survey Fee (per Section 28)£
Special Damage or Repair Fee (if any) (per Sec. 28.)£
Travelling Expenses (if chargeable)£
Second Surveyor's Fee (if any)£
Fees applied for, 18
Received by me, 18
A Campbell Holmes
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character assigned 100A
FRI. 24 FEB 1899
HULL CERTIFICATE WRITTEN. 27/2/99
© 2019 Lloyd's Register Foundation