

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office.

MUN 17 APL 1899

Date of writing Report *April 15th 99* When handed in at Local Office *18* Port of *London*
 No. in Reg. Book *1036* Survey held at *London* Date, First Survey *Mar 23* Last Survey *April 14th 1899*
 on the Machinery of the *Wood, Iron or Steel* *P.S. Star of Victoria* Master *Hart*
 Tonnage { Gross *3457* Net *2230* Vessel built at *Belfast* By whom *Workman Clark & Co* When *1887* Boilers, when made (Main) *1887* (Donkey) *1887*
 Registered Horse Power *325* Engines made at *915* Owners *(J. P. Corry & Co)* Port *Belfast* Voyage *New Zealand*
 No. of Main Boilers *2* If Surveyed Afloat or in Dry Dock *Victoria St. R.A. Dry Dock & J. Alway*
 No. of Donkey Boilers *1* Steam Pressure in Main Boilers *160 lb* in Donkey Boilers *80 lb* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Survey No. *SS. 70.3* Port *SS. 70.3*
 Particulars of Examination and Repairs (if any) *SS. 70.3*

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted under steam?

Has the propeller shaft been drawn and examined at this time?

If spare propeller shaft fitted, state whether new?

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft?

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Examined Main & Donkey Boilers internally & externally and Safety valves, also Cylinders, pistons, valves, pumps & Condenser, Sea Sledge connections, crank thrust, funnel, & propeller shafts, propeller and fastenings, found same all in good condition.

General Observations, Opinion, and Recommendation:— *This vessel's Machinery is now*

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9, 97, B.&M.S. 9, 97 or L.M.C. 9, 97, 140 lb., F.D., &c.)

in good condition & in my opinion the vessel is eligible for the record
L.M.C. 4. 99.

Office or Registration Fee (per Sec. 27)..... £

Survey Fee per Section 28)..... £ 5. 10. 0

Special Damage Fee (per Section 28)..... £ 11. 0

Travelling Expenses (if chargeable)..... £ 4. 19. 0

State if Certificate is required

Committee's Minute

Assigned

Fees applied for

19/4 18 99

Received by me,


20/4 18 99

MACHINERY CERTIFICATE

WRITTEN.

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

FRI. 20 OCT 1899



© 2019

Lloyd's Register Foundation

Lon 718 - 0124

Engines examined.
Main & Tank Boilers examined
Screw shaft examined

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible for
THE RECORD. — FmC. 499.

A.E.H.

19.4.99.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation