

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office

WED, 5 JUL 1899

Date of writing Report *14 July 1899* When landed in at Local Office *4 July 1899* Port of *London*

No. in Reg. Book *52* Survey held at *London* Date, First Survey *26 May 1899* Last Survey *26 May 1899*

on the Machinery of the Wood, Iron or Steel *S. S. 'Montali'* Master *S. Lueder*

Tonnage { Gross *2641* Net *1674* Vessel built at *Amberland* By whom *J. King* When *1896* YEAR. MONTH. *3*

Registered Horse Power *38.3* Engines made at *"* When *'96* Boilers, when made (Main) *'96* (Donkey) *'96*

No. of Main Boilers *2* Owners *Bullard King & Co* Port *London* Voyage *Natal*

No. of Donkey Boilers *1*

Steam Pressure— in Main Boilers *180* If Surveyed Afloat or in Dry Dock *Dry Dock* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

in Donkey Boilers *80*

Last Survey No. _____ Port _____

Particulars of Examination and Repairs (if any) *Pressing. +100 A. 5. 98 + L.M.C. 3. 98*

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? To what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler? To what pressure were they afterwards adjusted under steam?

Has the propeller shaft been drawn and examined at this time? *No.* If spare propeller shaft fitted, state whether new?

State the distance between lignum vitæ of stern bush and top of after bearing of screw shaft? *3/16"*

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? *Complete.*

Now done:—
Propeller Stern-bush and outside fastenings of sea connections examined and found in good order.

General Observations, Opinion, and Recommendation:—
 (State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.: thus, for example, B.S. 9,97, B. & M.S. 9,97 or L.M.C. 9,97, 140 (F.D., &c.)

The machinery of this vessel as now seen, is in good order and in my opinion eligible to remain as classed, without fresh record.

Office or Registration Fee (per Sec. 27)	£	:	:	Fees applied for
Survey Fee (per Section 28)	£	:	:	10
Special Damage Fee (per Section 28)	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	
				Received by me,
				10


P. Michie B.
 Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

State if Certificate is required _____

Committee's Minute _____

Assigned *As now*

FRI, 7 JUL 1899



LAN 18-0462

Has a Survey also been held on Ship? If so, is the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book.

*Certificate to be sent to

It is submitted that
this vessel is eligible to
remain as **CLASSED**.

SMW
5/7/99

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register
Foundation