



61435 Jon

leaky seam in fore part of stern frame caulked up  
To locate leak in stern frame, cement & woodwork  
in lazarette & deck was cut away, where required;  
now replaced and made good and the lazarette  
repainted.

Thos Robertson

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019

Lloyd's Register  
Foundation